

Misrepresentation of Intertek Certified Product Labels / Fausse représentation des étiquettes de produits certifiés Intertek

90 Minutes Fire Rated Door

Notification Type:	Misuse of Certification Mark / Mauvaise utilisation des marques de certification
Certification Type:	Not Intertek Certified

Notification

Intertek notifies public that we have been notified by the applicant that the labels identified below have been misrepresented as Intertek Certified. / Intertek informe le public que le demandeur nous a informés que les étiquettes identifiées ci-dessous ont été présentées à tort comme étant certifiées Intertek.

Company Identification

ARFAD International Industry Company

Product Identification

For misrepresentation of certified product labels, for ARFAD International Industry Company, 90 Minutes Fire Rated Door using the WH certification mark and documented under W/N 23029 – qty 1 certification labels with these serial numbers, (SN 000500). Label photo on Page 2

Concernant la présentation erronée des étiquettes de produits certifiés, pour la société ARFAD International Industry Company, porte coupe-feu 90 minutes utilisant la marque de certification WH et documentée sous le numéro W/N 23029 – quantité 1 étiquette de certification avec les numéros de série suivants (SN 000500). Photo de l'étiquette en page 2

Hazard Involved

Not certified by Intertek. / Non certifié par Intertek.

What To Do

Use should be immediately discontinued and return to the point of purchase and the labels should be removed and returned to Intertek/ L'utilisation doit être immédiatement interrompue et retournée au point d'achat et les étiquettes doivent être retirées et retournées à Intertek.

Published: November 18, 2025
Revised:

Public Notice ID: 2025-109
Page 2 of 2

Photos and Images

